

# Effect of Heated Cuffs on PEMFC Performance

Non-heated exposed fittings can be a source of cold spots, resulting in condensation and instability in cell performance

Heated cuffs: **ON** **OFF** **ON**

